

EXHIBIT 37

From: Peter Judis
To: Brian Stouffer
CC: John Sprague; John Zuzelski; Terrence E Connolly
BCC:
Sent Date: 2012-06-28 20:55:35:000
Received Date: 2012-06-28 20:55:36:000
Subject: Cobalt Key Cylinder Issue - History Of Steering Column Changes Attached
Attachments:

Brian,

As a follow up item from our 21JUN2012 meeting, I have attached a list of all the steering column changes for the Chevy Cobalt from 2005 - 2008 model years. The description of each change is shown in Row 4. I could not find any changes that would have effected the ignition lock housing (part of steering column) or ignition key rotational torque.

Pete
Steering Column BFO

----- Forwarded by Peter Judis/US/GM/GMC on 06/28/2012 04:45 PM -----



Terrence E
Connolly/US/GM/GMC

To Peter Judis/US/GM/GMC [REDACTED]

cc

06/21/2012 01:56 PM

Subject Fw: Cobalt Key Cylinder Issue (VEC, c/r 1E26-16 Green or MML: 866-226-3606 a/c 6637671
Fed will host 4504)

Thanks!

Terry Connolly
[REDACTED]

----- Forwarded by Terrence E Connolly/US/GM/GMC on 06/21/2012 01:54 PM -----

Cobalt Key Cylinder Issue (VEC, c/r 1E26-16 Green or MML: 866-226-3606 a/c 6637671 Fed will host 4504)

Calendar Entry Type

Thu 06/21/2012 2:00 PM - 2:30 PM

Terrence E Connolly

Chair: Jim Federico/US/GM/GMC
Sent By: Colleen T Brown/US/GM/GMC

Brian Stouffer/US/GM/GMC [REDACTED], Brian Thompson/US/GM/GMC [REDACTED], Bruce Jackson/US/GM/GMC [REDACTED], Carmen Benavides/US/GM/GMC [REDACTED], David Carey/US/GM/GMC [REDACTED], David DeFrain/US/GM/GMC [REDACTED], Doug Wachtel/US/GM/GMC [REDACTED], Jeffrey Konchan/US/GM/GMC [REDACTED], John Capp/US/GM/GMC [REDACTED], John Sprague/US/GM/GMC [REDACTED], John Zuzelski/US/GM/GMC [REDACTED], Kristen M. Siemen/US/GM/GMC [REDACTED], Lisa D. Weber/US/GM/GMC [REDACTED], Terrence E Connolly/US/GM/GMC [REDACTED], William J. Kemp/US/GM/GMC [REDACTED]

The following attachments were deleted at 7:55:36 AM on 9/26/2012

10 - GMX001 Chevy Cobalt Steering Column Part History.xls